Idaho PUC Pipeline Safety Inspection Summary

Inspector(s):	Perkins, Ulmer	and Russo	Date(s):	1-3May 2019
			T	
Company/Owner:	Intermou	intain Gas Company	Unit/OPID:	8160
Inspection Type & Time (1	day 0.5 day)	Total Ir	spection Days:	5.5
inspection Type & Time (1	uay, 0.3 uay)	Totalii	ispection Days.	3.3
Standard: Construction:	5.5 Training:	(T)(D) Integrity Management:	Incident:	
M/M: Follow-up:	OQ:	Damage Prevention:	D&A:	
Inspection Summary				
A construction inspection was performed on DAS-CO, a contractor for Intermountain Gas Company.				
<u>1-2 May 2019:</u> (5.0 Construction)				
Crew was installing a 6" PE plastic main as part of a main replacement, new service lines and removal of HPSS project# 367-0330				
Areas observed during this project were: Other utility location, fusing, excavation, pot holing, abandoning, main line installation (tracer wire), line locating and backfilling.				
3 May 2019: (.5 post Construction) Type construction report.				
Attachments: IPUC Form 4 Construction Inspections DAS-CO Daily Itineraries located in file for the project. OQ's for all observed employees are located in file for the project. Photo's are located in file for the project.				
Corrective Action Required:		ow-up Required: Ye		Х
Yes No	X		by (date):	
Inspector (Lead):	I A ali	2/2	Date:	
Bruce Perkins	74- C/A	Polity	3 MgY/	7
Reviewer: Darrin Ulmer	1 Vartall	1/1/	Le May	2019